



Volkswagen Crafter

35 Kasten Trendline HD, 4MOTION





SPECIFICATION

TESTED MODEL	Volkswagen Crafter — 35 Kasten Trendline HD, 4MOTION				
BODY TYPE / CATEGORY	Monocoque / N1				
KERB / PAYLOAD / TEST WEIGHT	2548 kg / 952 kg / 3020 kg				
APPLIES TO	2 nd generation 2017 to present				

SAFETY EQUIPMENT

SAFETY ASSIST	Driver	Passenger	
Seat Belt reminder	۲	0	

ADVANCED DRIVER ASSISTANCE SYSTEMS (on tested variant)				
AEB Car-to-Car	0			
AEB Pedestrian	×			
AEB Cyclist	×			
Lane Support Systems	0			
Speed Assist Systems	0			
Attention Assist	0			

STANDARD

FITTED AS OPTION

 \cap

NOT AVAILABLE

Verdict

All in all, the Crafter emerges with a silver medal from Euro NCAP's tests. Its AEB system lacks the more sophisticated elements of the gold medallists, like recognition of vulnerable road users, but a good amount of safety equipment is offered to those consumers looking for safety.

For detailed comments see below.




SAFETY ASSIST PERFORMANCE


SAFETY ASSIST PERFO		 	
AEB CAR-TO-CAR			/ 30 Pts
Туре	AEB & FCW		
Operational From	8 km/h		

Autobrake function only


Approaching a stationary car




Approaching a stationary car




Approaching a slower moving car




Approaching a braking car




Approaching a stationary car



Approaching a slower moving car



Approaching a slower moving car






44%

Total


SAFETY ASSIST PERFORMANCE

Driver reacts to warning (Forward Collision Warning - FCW)


Approaching a stationary car




Approaching a stationary car




Approaching a slower moving car




Approaching a braking car




Approaching a stationary car



Approaching a slower moving car



Approaching a slower moving car




WEAK

Euro NCAP © 2022 Volkswagen Crafter 3/7




SAFETY ASSIST PERFORMANCE	Total	44%
AEB PEDESTRIAN		N/A


Adult crossing the road



Adult along the roadside




Child running from behind parked vehicles




N/A

AEB CYCLIST

Cyclist crossing



Cyclist along the roadside







44%

10.0 / 15 Pts

Total

SAFETY ASSIST PERFORMANCE

LANE SUPPORT 15.0 / 20 Pts

Туре	ELK/LKA, LDW & BLIS
Operational From	60 km/h
PERFORMANCE	
Emergency Lane Keeping (ELK) / Lane Keep Assist (LKA)	
Lane Departure Warning (LDW)	
Blind Spot Information System (BLIS)	

EED ASSISTANCE		5.3 / 15 Pts
Speed Limit Information Function	Camera based	
Speed Limitation Function	Manually set	

OCCUPANT STATUS MONITORING

DRIVER MONITORING			
Attention Assist Driver			

SEATBELT REMINDER	Driver Seat	Front Passenger	
Visual Warning			
Audible Warning			_



good adequate marginal weak poo					
	GOOD	ADEQUATE	MARGINAL	WEAK	POOR
		· ·			

SAFETY ASSIST PERFORMANCE

GOOD

POOR



Comment

Autonomous emergency braking (AEB), together with forward collision warning (FCW) is available as an option and was fitted to Euro NCAP's test vehicle. In tests of the system's functionality with a car in front, there was no response to a stationary or slower-moving car when it was significantly offset to the right or left. There was better performance when the target vehicle was straight ahead or slightly offset and overall performance was adequate. The system does not recognise vulnerable road users like pedestrians and cyclists.

A lane support system is offered as an option and comprises lane departure warning (LDW), which warns the driver if the vehicle is drifting out of lane, and lane keep assist (LKA), which gently steers the vehicle back into lane. Both of these functions worked well, although LKA allowed the vehicle to drift too far over the lane edge in some of the test scenarios. The system also intervenes more aggressively in some emergency situations. This functionality is, by default, turned on at the start of every journey and, with good performance in Euro NCAP's tests, the system was rewarded. Additional lane support is provided by the optional blind-spot information system (BLIS).

A camera-based speed assistance system uses traffic-sign recognition to identify local speed limits and presents this information to driver who can then set the limiter as appropriate. The system worked well but the limiter was unable to maintain the speed with sufficient accuracy to be awarded points.

A seatbelt reminder is provided as standard only for the driver's seat but is available for the passenger seat. The Crafter has an optional driver-state monitoring system which identifies steering patterns which are characteristic of fatigued or impaired driving and indicates to the driver that he should take a break. However, as the system is not switched on by default, it did not meet Euro NCAP's requirements.



FITMENT

		OMOUS ENCY BR ⁄IS	AKING	LANE S SYSTEM	UPPORT 1S		SPEED SYSTEN			ANT STA ORING SY	
	AEB Car-to-Car	AEB Pedestrian	AEB Cyclist	Emergency Lane Keeping / Lane Keep Assist	Lane Departure Warning	Blind Spot Information System	Speed Limit Information Function	Speed Limitation Function	Seat Belt Reminder - Driver	Seat Belt Reminder - Passenger	Attention Assist
Austria	0	×	×	0	0	×	0	0		0	0
Belgium	0	×	×	0	0	×	0	0		0	0
Bulgaria	0	×	×	0	0	×	0	0		0	0
Croatia	0	×	×	0	0	×	0	0		0	0
Cyprus	0	×	×	0	0	×	0	0		0	0
Czech Republic	0	×	×	0	0	0	0	0		0	0
Denmark		×	×	0	0	×	0			0	0
Estonia	0	×	×	0	0	×	0	0		0	0
Finland	0	×	×	0	0	0	0	0		0	0
France	0	×	×	0	0	×	0			0	0
Germany	0	×	×	0	0	×	0	0		0	0
Greece	0	×	×	0	0	0	0	0		0	0
Hungary	0	×	×	0	0	0	0			0	0
Ireland	0	×	×	0	0	0	0	0		0	
Italy	0	×	×	0	0	×	0	0		0	0
Latvia	0	×	×	0	0	×	0	0		0	0
Lithuania	0	×	×	0	0	×	0	0		0	0
Luxembourg	0	×	×	0	0	×	0	0		0	0
Malta	0	×	×	0	0	×	0	0		0	0
The Netherlands	0	×	×	0	0	×	0	0		0	0
Poland	0	×	×	0	0	0	0	0		0	0
Portugal	0	×	×	0	0	×	0			0	0
Romania	0	×	×	0	0	0	0	0		0	0
Slovakia	0	×	×	0	0	0	0	0		0	0
Slovenia	0	×	×	0	0	0	0	0		0	0
Spain	0	×	×	0	0	×	×	0		0	×
Sweden		×	×	0	0	0	0	0		0	0
United Kingdom		×	×	0	0	×	×	0		0	

For latest fitment info for your market, check our website.

X NOT AVAILABLE

VEHICLE NOT SOLD